

## Fixes and Enhancements

# Creo Elements/Direct® Modeling 20.1.4.0

---

Please find below the list of fixes and enhancements - as of September 28<sup>th</sup>, 2020 - that have been implemented for Creo Elements/Direct Modeling and Creo Elements/Direct 3D Access 20.1.4.0.

<b>ID</b>	<b>Description</b>	<b>Module</b>	<b>Release</b>
6787223	Creating a parallel construction line with a string value causes a system crash	2D Geometry	20.1.0.0
7034293	Unable to save a package file after having sent a model to Creo Simulate	Advanced Mechanica	20.1.0.0
7136660	Update of a 3d model doesn't work with Creo Simulate	Advanced Mechanica	20.1.0.0
6745336	Update of flat not possible and reports the error: Check red elements in flat drawing - Open edge	Annotation	20.1.0.0
6465760	The old type's thread dimension is converted automatically although it's different with the current "Dim Thread Setting" in Creo Elements/Direct Modeling	Annotation - Dimension	20.1.0.0
6380661	Typo in 10500th line of Japanese pesd_am.ms	Annotation - Hatch	20.1.0.0
6380637	Error message at creating a new Drawing Template without no active viewset is not localized to Japanese.	Annotation - Settings	20.1.0.0
6372943	Symbols of special characters (Between, StatTol, EnvReq, ReciProcReqs, TangentPlane and FreeState) are missing. Also, if user tries to use them in text, they get overlapped on next text character in the text line.	Annotation - Text	20.1.0.0
6492567	In 19.0 edge colors set with the Edge Property are overwritten by the active part color. Worked in 17 and 18 - regression	Base Functionality - Modeling	20.1.0.0
6630945	Unable to load some PKG files with error message: PTC Creo Elements/Direct Modeling could not unpack the file "x.pkg". Either this file does not contain a saved package file, you do not have sufficient virtual memory, or no space is left in the directory.	Base Functionality - Modeling	20.1.0.0
6747224	Thumbnail doesn't work when View as "Large	Base	20.1.0.0

Copyright © 2020 PTC Inc.

	icons" in Windows browser if just install Creo Elements/Direct Modeling one version 20.0 only on machine.	Functionality - Modeling	
6808384	Cursor freezes after creating a star profile in Creo Elements/Direct Modeling	Base Functionality - Modeling	20.1.0.0
6925090	The list of "Preset Explode" displays randomly, the order is not the same as "Configurations" set on an original model on Creo Elements/Direct Modeling	Base Functionality - Modeling	20.1.0.0
6955024	Error Message Not enough disk space even there is enough available	Base Functionality - Modeling	20.1.0.0
7031998	Creo View Adapter fails to generate STL file as additional file using publish rule	Base Functionality - Modeling	20.1.0.0
7231683	Modeling start time keeps going up unless the machine is restarted	Base Functionality - Modeling	20.1.0.0
6402001	Unable to un-route or re-route existing harness	Cabling	20.1.0.0
7233713	A new copy of harness is not possible because text box to enter "New harness name" is inactive.	Cabling	20.1.0.0
7266285	LISP error while adding cable to existing unit using ecad file.	Cabling	20.1.0.0
7266322	"Edit Cancel" button on Add Cable tab on Cable Library dialog hides the contents of Library Content tab	Cabling	20.1.0.0
7266330	Cabling: When a connector is chosen in Move Connector, "LISP error: The function MIP_SC::GET_ALL_SNAP_CSYS is undefined." is displayed.	Cabling	20.1.0.0
7266333	When using Pin to Pin functionality, select connection on start point, it is possible to modify position free, but not possible for end point.	Cabling	20.1.0.0
7266342	Regression: Error when move a connector - Error LISP: The function MIP_SC::GET_ALL_SNAP_CSYS is undefined	Cabling	20.1.0.0
7266431	No response when copying a harness in Cabling module.	Cabling	20.1.0.0
7266454	After selecting the segment, offset value is not editable in "offset flatcable segment dialog box".	Cabling	20.1.0.0
7271947	Unexpected error message displayed during command execution and output wire was displayed in wireframe mode.	Cabling	20.1.0.0
7272068	[Cabling] Unable to copy a harness if harness	Cabling	20.1.0.0

	assembly is read-only status		
7267019	Dynamically moving a face back and forth in Modeling creates a Fatal Exception.	Faces & Rec. Features	20.1.0.0
7267072	Move Face leads to strange results on the ends of a slot (cylindrical faces)	Faces & Rec. Features	20.1.0.0
6378364	"Plus" and "spaces" are not removed from model name when backward save the model	Filing - Modeling	20.1.0.0
6748590	"Space" and "Plus sign" isn't removed from the part name when saving the part from Creo Elements/Direct Modeling 20 to Creo Elements/Direct Modeling 19	Filing - Modeling	20.1.0.0
7044322	DXF/DWG import configurator does not work if there are spaces in path.	Interfaces 2D	20.1.0.0
6415690	CEDM 19.0.6.34 M060 [REG RR]: Export to .sat files is failing. Error is "Translation to native format failed".	Interfaces 3D	20.1.0.0
6440525	System hangs on and it is not possible to load assembly *.iam files from Inventor 2016	Interfaces 3D	20.1.0.0
6468409	Exporting a model to Parasolid takes to long	Interfaces 3D	20.1.0.0
6603062	Solid Edge assembly does not load correctly	Interfaces 3D	20.1.0.0
6672969	When load a SolidEdge assembly file in Creo Elements/Direct Modeling, the import result is wrong. But it imports well if load all the related part file *.par one by one. Also, this assembly can be imported Creo Parametric 3.0 successfully	Interfaces 3D	20.1.0.0
6780058	Unable to export the model as XVL on Windows 10	Interfaces 3D	20.1.0.0
6946453	While importing the .bdl file as 'Associative Drawing with 3d model', the Cutaway View is not getting imported correct.	Interfaces 3D	20.1.0.0
6972256	Name of saved eDrawing file is always became "P.easm" even if saving eDrawings file with Japanese characters for file name	Interfaces 3D	20.1.0.0
6995247	Direct CAD interfaces missing setup_ug_nx11.exe	Interfaces 3D	20.1.0.0
7029322	Load SolidWorks, SolidEdge, NX or Inventor data (native format) into Modeling. After this step, saving the data in a .PKG or a .BDL is not possible on Windows 10 machines.	Interfaces 3D	20.1.0.0
7126267	Add Support for SolidWorks 2018 and Inventor 2018.	Interfaces 3D	20.1.0.0
7229966	In the PVZ file output from Creo Elements/Direct Modeling, the arrangement order of components is different on Creo Illustrate.	Interfaces 3D	20.1.0.0

6592322	Update of a 3d model doesn't work with Creo Simulate 4.0 and Creo Elements/Direct Modeling Version 20	Interfaces 3D - Creo	20.1.0.0
6635037	When loading a model created with Creo Parametric 4.0 with Creo Elements/Direct Modeling, Japanese assembly name / component name characters are broken.	Interfaces 3D - Creo	20.1.0.0
6651184	Import of .pkg file results with wrong geometry in Creo Parametric 3.0	Interfaces 3D - Creo	20.1.0.0
6819021	The wrong Creo Parametric's release is explained in HELP CENTER to import the native data to Creo Elements/Direct Modeling	Interfaces 3D - Creo	20.1.0.0
6821309	CED files are not opening in Windows 10-64 bit Creo 4.0 second time onwards.	Interfaces 3D - Creo	20.1.0.0
6828773	Configurations are not getting transferred as Explode States when importing the *.bdl files into Creo.	Interfaces 3D - Creo	20.1.0.0
6983968	Unable to save to PKG file after load Creo Parametric file and STEP file on Traditional Chinese Windows 10 in Creo Elements/Direct Modeling 20.0 M020	Interfaces 3D - Creo	20.1.0.0
7206668	When starting Creo Elements/Direct Modeling 20.0 M020, it output the following info and cannot load STEP file:"Activation of module "STEP" failed: "LISP error: Loading shared library failed for granite"	Interfaces 3D - STEP	20.1.0.0
6617568	All Creo Elements/Direct update protected applications running latest revision are satisfied using a license in earlier revision and do not request an update to latest revision.	Licensing - Modeling	20.1.0.0
6383786	Japanese localization issue for "sd_cadcam.ms" file in Creo Elements/Direct Modeling	Machining Features	20.1.0.0
7097187	Documentation: Representation > To Front does not move a sketch in front of the drawing nor a picture in front of the drawing	Modeling	20.1.0.0
6371015	User can De-select any options for "Usage as" when creating a new model to PartLibrary catalog.	PartLibrary	20.1.0.0
6372424	When loading a custom part stored into Part Library using "Original" template, a new CAD Document with the prefix "SDP" added is saved to Workspace, the upload is failed with "a datastore uniqueness constraint violation" conflict	PartLibrary	20.1.0.0
6404735	The library part that created by Administration menu is not removed.	PartLibrary	20.1.0.0

6530359	Update required for PartLibrary screw type DIN 24035 in Creo Elements/Direct Modeling Update required for PartLibrary screw type DIN 24035 in Creo Elements/Direct Modeling	PartLibrary	20.1.0.0
6384042	Performance improvement in PCB Result: The sample board which took 308 seconds to import earlier, now takes 18 seconds!	PCB/IF	20.1.0.0
7056422	Wrong version number when installing SDServer for Creo Elements/Direct Modeling	Remote	20.1.0.0
6393876	Function Cut Slot in a sheet metal cone doesn't create slot with a constant distance i	Sheet Metal	20.1.0.0
6652270	Cut-slot function is not working.	Sheet Metal	20.1.0.0
6689122	Wrong corner relief created by a new lip causes wrong flat	Sheet Metal	20.1.0.0
6463163	If Bend Angle is very small an error appears	Sheet Metal - Fold/Unfold	20.1.0.0
6621597	Creating a flat view in Annotation the error message appears: Errors occurred during flat generation. Check red elements in flat drawing.- Open edge.	Sheet Metal - Fold/Unfold	20.1.0.0
6621953	Slot being attached to bend zone in unfolded sheet using Unfold 2D results in wrong color for punch line	Sheet Metal - Fold/Unfold	20.1.0.0
6621995	Flat view in Annotation or Unfold 2D in Sheet Metal has the wrong flat color in Sheet Metal	Sheet Metal - Fold/Unfold	20.1.0.0
6735716	Regression: If Bend Angle is between 1 and 4 an error appears when creating a flat view	Sheet Metal - Fold/Unfold	20.1.0.0
6745332	Unfold 2D produces unusable results in Creo Elements/Direct Modeling 19.0	Sheet Metal - Fold/Unfold	20.1.0.0
6745340	Missing geometry in flat	Sheet Metal - Fold/Unfold	20.1.0.0
7111506	Modeling stopped working when unfolding a sheet metal part	Sheet Metal - Fold/Unfold	20.1.0.0
6384566	While publishing additional file format WVS job monitor logs shows message " Processing additional files: No of Files " but does not describe which additional file type it is generating.[Please check the attachment]	WGM for Modeling	20.1.0.0
6393929	The "Save to Workspace" from the file tab results in a entry in the workspace with a non synchronized file name and no number.	WGM for Modeling	20.1.0.0
6470880	Lock functionality for CEDM WGM does not work at all	WGM for Modeling	20.1.0.0
6493882	Define Library Used by Application preference does not work	WGM for Modeling	20.1.0.0

6733315	Create and activate a new workspace takes long	WGM for Modeling	20.1.0.0
6773224	Remove assembly from workspace takes long	WGM for Modeling	20.1.0.0
6938563	Unable to assign attribute from Creo Elements/Direct Modeling to Windchill Real Number with Units. It is recognized as String type attribute	WGM for Modeling	20.1.0.0
7061817	Unique identifiers of the memberlink are not retained upon EPM Document iteration	WGM for Modeling	20.1.0.0
7124342	Migrated assemblies fail to load in Windchill Workgroup Manager for Creo Elements/Direct Modeling	WGM for Modeling	20.1.0.0
7252065	While publishing, the SolidDesigner.exe process hangs and jobs fails Then if we manually kills the SolidDesigner.exe then worker works again	WGM for Modeling	20.1.0.0
7090042	Bolt circle causes problem when exporting drawing to DXF in Annotation	Annotation	20.1.1.0
7582048	When printing a drawing in Landscape mode in Creo Elements/Direct Modeling the drawing will be shown in Portrait orientation	Annotation	20.1.1.0
6536295	Creo Elements/Direct Modeling corrupts the drawing when saving it.	Annotation - View Update	20.1.1.0
6383763	Unable to import specific DWG into Creo Elements/Direct Modeling Annotation by DWG (*.dwg) or Import 2D (*.mi, *.bi, *.dxf, *.dwg, *.igs, *.iges), but imports well in Creo Parametric 3.0 and AutoCAD 2013	Interfaces - DWG/DXF	20.1.1.0
7496932	7-zip potential vulnerability identified in Creo Parametric 7-zip Memory Corruption Vulnerability (CVE Number CVE 2018 10115)	Interfaces 3D - Creo	20.1.1.0
7564305	Pkg from Creo Direct Modeling is opened empty with no geometry in Creo Parametric	Interfaces 3D - Creo	20.1.1.0
5902266	Renaming the model in the common space giving the name a name with a "/" in it, it can't be loaded any more	Modeling Integration	20.1.1.0
6141086	sd-uwgm-set-model-attribute generates segmentation violation when changing string attribute from NIL to empty sd-uwgm-set-model-attribute generates segmentation violation when changing string attribute from NIL to empty string "" in Modeling 19.0 M040	Modeling Integration	20.1.1.0
7158008	Import fails for CEDM assembly with a missing dependent	Modeling Integration	20.1.1.0
7372278	Cut Slot fails in case of conical and cylindrical parts having Body transformation	Sheet Metal	20.1.1.0

5604523	Bend text jumps in a flat view of a sheet metal part after view update	Sheet Metal - Fold/Unfold	20.1.1.0
6189051	REGRR [Modeling 19.0 M050 ->M060] : Data fails to Open in Modeling resulting in a Modeling crash, when CEDM is launched from WGM and CEDM has default configuration of creating start parts upon opening. Reproducible with CEDM 20.0	WGM for Modeling	20.1.1.0
6656481	Storing drawing fills in IBA values of previously loaded drawing	WGM for Modeling	20.1.1.0
6965804	CEDM hangs when import to workspace is done after loading a part with command (sd-uwgm-element-load)	WGM for Modeling	20.1.1.0
7234056	WGM & CEDM side fix to support Windchill Server side customization requirement for Liebherr Albatros	WGM for Modeling	20.1.1.0
7368672	Defect 7350179 -> SPR: New Tagging Approach: File Name and other system attributes are seen in CEDM structure browser for Relation file in CEDM.	WGM for Modeling	20.1.1.0
7369903	Defect 7265014 -> SPR: Loading of Finish/Semi-Finish Data in CEDM session when Finish/Semi-Finish data is already open loads additional irrelevant data	WGM for Modeling	20.1.1.0
7395077	CEDM: WGM function 'sd-uwgm-set-commonname' is not working.	WGM for Modeling	20.1.1.0
7473975	Crashes when loading assembly in Workgroup Manager for Creo Elements/Direct Modeling	WGM for Modeling	20.1.1.0
7479430	File name and file number is not synchronized, and file number extension is dropped, when part is saved via Global "save to Workspace".	WGM for Modeling	20.1.1.0
7508744	SingleFile option does not work for Multi sheet drawings in Workgroup Manager for Creo Elements/Direct Modeling	WGM for Modeling	20.1.1.0
7524023	Getting error "An orphaned inseparable object is found which cannot uniquely related to its inseparable master" while loading an inseparable assembly in Creo Elements/Direct Modeling	WGM for Modeling	20.1.1.0
7525225	[CEDM 20.1 M010 specific] : Doing 'Compare model versions' in CEDM 20.1 M010 Build 6 fails	WGM for Modeling	20.1.1.0
7588167	Migrated drawings are not recognized as existing upon save	WGM for Modeling	20.1.1.0
7594616	Modeling crash while updating inseparable child i	WGM for Modeling	20.1.1.0
7723490	REGBB [20.0.4.20 -> 22] & [20.1.1.12 -> 14] :	WGM for	20.1.1.0

	Activation of Windchill module fails from CEDM which results in CEDM hang/crash	Modeling	
5937324	Cannot select many 2D edges to be projected onto another workplane in Creo Elements/Direct Modeling	Workplanes/W orkplaneSets	20.1.1.0
8041154	[REG-RR-CEDM 20] Help documentation: context sensitivity has been broken for 3D Bridge Curve and 3D Conical Curve	3D Curve	20.1.2.0
8045948	[REG-RR-CEDM 20] Help documentation: context sensitivity has been broken for Create Bolt Circle (Annotation).	Annotation - Dimension	20.1.2.0
6248624	German version of pesd.ms file of Creo Elements/Direct Modeling contains typos in lines 29169, 51092 and 51113	Base Functionality - Modeling	20.1.2.0
7560004	In Creo Elements/Direct Modeling configurations cannot be deleted or modified if the name of the parent assembly contains a blank	Configuration	20.1.2.0
7954021	CEDM 20.1.1.0: Broken links in CED Modeling Advanced Documentation.	Installation - Modeling	20.1.2.0
7994056	CEDM 20.0: NX part/assembly drag-drop limitation is wrongly mentioned in Help documentation.	Interfaces 3D	20.1.2.0
7785863	wrong display of an imported creo elements / direct modelling bundle	Interfaces 3D - Creo	20.1.2.0
7812363	Drawing views imported from Bundle.bdl of Creo Elements/Direct Modeling are not associated to the model and warning is shown "Some views are not associative with selected 3D model"	Interfaces 3D - Creo	20.1.2.0
7847565	Importing .mi file in Creo Parametric shows misplaced views vs in Creo Elements Direct with option Drawing Associative with 3D Model	Interfaces 3D - Creo	20.1.2.0
7829537	The portable license create with LicensingConfiguration.exe from Portable License Enabler delivered with Modeling 20.1 opens Modeling 17.0 .. 20.0 but not Modeling 20.1	Licensing - Modeling	20.1.2.0
7729885	Geometry is lost when saving models loaded as structure in Windchill Workgroup Manager for Creo Elements/Direct Modeling	Modeling	20.1.2.0
8002339	User unable to Add eDrawing file from Modeling to Model Manager.	Modeling	20.1.2.0
8032804	User unable to Add eDrawing file from Annotation to Model Manager	Modeling	20.1.2.0
8039323	Not able to export or publish "XVL" format as an additional output on Windows 10 system [Please find the attached mail for more details]	Modeling	20.1.2.0



6164025	CEDM [Help]: help documents should be updated for topic "granite save options"	User Interface - Modeling	20.1.2.0
7471740	Undo for loading a drawing with embedded frame leads to crash	WGM for Modeling	20.1.2.0
7525225	[CEDM 20.1 M010 specific]: Doing 'Compare model versions' in CEDM 20.1 M010 Build 6 fails	WGM for Modeling	20.1.2.0
7729885	Geometry is lost when saving models loaded as structure in Windchill Workgroup Manager for Creo Elements/Direct Modeling	WGM for Modeling	20.1.2.0
7757566	Show verbose error with "Update failed as a result of an error in CAD tool" and Fix failures of Update>OK scenario	WGM for Modeling	20.1.2.0
7802941	d-uwgm-element-load does not return SEL_ITEM	WGM for Modeling	20.1.2.0
7817789	Delete assembly in Modeling with activated WGM leads to "Action failed ... " error	WGM for Modeling	20.1.2.0
7870105	Update All - OK fails - Models in session cannot be replaced	WGM for Modeling	20.1.2.0
7899067	After checking out assembly with stock-finish relation and changing instance information (like change name) Save to workspace fails with name conflict	WGM for Modeling	20.1.2.0
7986261	Export List to PTC Creo Elements/Direct Modeling Getting error: "the owning assembly of the BOM could not be found" when trying to create a BOM	WGM for Modeling	20.1.2.0
8041356	Delay Autonumber Generation causes 'Name' attribute to have duplicate extensions in Windchill Workgroup Manager for Creo Elements/Direct Modeling	WGM for Modeling	20.1.2.0
8089706	Export of BOM Report of any type to CEDM fails with error.	WGM for Modeling	20.1.2.0
6724580	Drawing fails to publish using CAD worker when iterated after first Check In, either through CEDM or using re-submit on WVS job monitor.	Annotation	20.1.3.0
7988073	Annotation View Copy: Detail view text is not updated while copying view from one sheet to another.	Annotation - View	20.1.3.0
8214816	CEDM 20.0 M050: Integration of PTC OEM module for XVL Converter 15.1	Interfaces 3D	20.1.3.0
9254934	Supported version of ACIS SAT is incorrectly described in Creo Elements/Direct Modeling Help Center	Interfaces 3D	20.1.3.0
9254934	Supported version of ACIS SAT is incorrectly described in Creo Elements/Direct Modeling Help Center	Interfaces 3D	20.1.3.0

7561979	LISP Error "NIL is not of type DSM::SIMPLE-ENTITY" is thrown when tree nodes parts having Drawing & views are expanded in structure browser for a Customer dataset	Modeling Integration	20.1.3.0
8384852	When importing from pcb library, models are missing when spaces are in the names in the PCB Module	PCB/IF	20.1.3.0
8227970	Missing explanation for keyboard shortcut "F10" and "Alt" in help center of Creo Elements/Direct Modeling	User Interface - Customization	20.1.3.0
8227970	Missing explanation for keyboard shortcut "F10" and "Alt" in help center of Creo Elements/Direct Modeling	User Interface - Customization	20.1.3.0
8227993	Insufficient explanation for keyboard shortcut "Ctrl + Q" at help center of Creo Elements/Direct Modeling	User Interface - Customization	20.1.3.0
8227993	Insufficient explanation for keyboard shortcut "Ctrl + Q" at help center of Creo Elements/Direct Modeling	User Interface - Customization	20.1.3.0
7846041	Floating Toolbars will appear on unique position after restart in Creo Elements/Direct Modeling 20.0, 20.1	User Interface - Modeling	20.1.3.0
5816768	Annotation drawings cannot be loaded vis the IKIT function sd-uwgm-element-load	WGM for Modeling	20.1.3.0
7937249	Unable to publish file as DXF using Creo view adapter 5.0	WGM for Modeling	20.1.3.0
8076303	Undo / REDO after loading a drawing with embedded frame creates a second sheet	WGM for Modeling	20.1.3.0
8190076	Cannot load models with a + sign or other special characters in the name after a rename	WGM for Modeling	20.1.3.0
8218575	[CEDM Specific]: "Update failed as a Result of Error in CAD tool" is thrown after uploading part on a Windchill server which has specific customization for Naming & Numbering.	WGM for Modeling	20.1.3.0
8222079	Export BOM Report fails, when any WTPart Product structure is renamed in Windchill and Exported	WGM for Modeling	20.1.3.0
8261576	CEDM 20.1 specific: Annotation warning seen while Exporting multiple MI files in UI manual mode.	WGM for Modeling	20.1.3.0
8399173	PDM operations executed on assembly components from the Creo Elements Direct/Modeling 'Mini Toolbar' are applied to the top assembly instead of the component	WGM for Modeling	20.1.3.0
8408668	CEDM WGM: Corrupt data can be created and checked into Windchill when using inseparable	WGM for Modeling	20.1.3.0

	assemblies		
8708456	Automation specific: 'SimulateCommandEx' command does not work for data new in session. Requires File Name field.	WGM for Modeling	20.1.3.0
8711666	Load performance of CED Modeling 20.0 M050 up to 7 times slower than every previous version	WGM for Modeling	20.1.3.0
8111046	Unable to import a compressed 2d Drafting drawing in the current workplane in Creo Elements/Direct Modeling	Workplanes/WorkplaneSets	20.1.3.0
7319133	Copy Sheet does not Copy Texts, Geometries whose Owner is Sheet.	Annotation	20.1.4.0
7499911	Creo Elements/Direct Modeling does not offer pen transformation or finer pen width controls	Annotation	20.1.4.0
9521380	User unit definition for importing DXF / DWG files won't be executed in Creo Elements/Direct Annotation.	Annotation	20.1.4.0
2817799	Modeling exits prematurely if rename the sheet name to "no strings" in Drawing Browser	Annotation - Drawing & Sheet	20.1.4.0
10137969	Representation from CAD Worker uses different format scale as original Creo Elements/Direct Modeling file	Annotation - Drawing & Sheet	20.1.4.0
6380659	Typo in 10500th line of Japanese pesd_am.ms	Annotation - Hatch	20.1.4.0
9538675	Modeling has poor performance on Windows 10 while structure browser is fully expanded on large assemblies	Base Functionality - Model Manager	20.1.4.0
7366385	It's slow when using position command or using space key to invoke mini toolbar for the first time in Creo Elements/Direct Modeling	Base Functionality - Modeling	20.1.4.0
9812208	CED Modeling crashes randomly at different operations	Base Functionality - Modeling	20.1.4.0
9868113	Modeling start time keeps going up unless the machine is restarted	Base Functionality - Modeling	20.1.4.0
9876952	The first time after startup, the display of the mini toolbar by the space key is delayed	Base Functionality - Modeling	20.1.4.0
10084257	To port sanity check fixes (Liebherr random crashes) in all CED active streams	Base Functionality - Modeling	20.1.4.0
10103644	Modeling Crashes by missing LISP functions.	Base Functionality - Modeling	20.1.4.0
10264426	Modeling Crashes by missing LISP functions on	Base	20.1.4.0

	structure browser.	Functionality - Modeling	
9874202	Configurations not working when loaded using STRUCTURE and then changed load type to FULL	Filing - Modeling	20.1.4.0
4641221	No geometry appears when importing a particular .sdpc file saved by Creo Elements/Direct. No geometry appears when importing a particular .sdpc file saved by Creo Elements/Direct	Interfaces 3D	20.1.4.0
9645487	3DPDF Output option is not getting published successfully as Additional Output	Interfaces 3D	20.1.4.0
9920257	IGES/SAT import/export fails in Creo Elements/Direct Modeling	Interfaces 3D	20.1.4.0
5811731	How to set linetypes, colors and widths in (pdf /pvz)Worker configuration for Annotation drawings	Interfaces 3D - Creo	20.1.4.0
6820523	For few components Internal name is not unique for unique Windchill CADname (=winchill filename).	Interfaces 3D - Creo	20.1.4.0
7090516	CED Configurations are not importing as Explode states if CED configurations names contains "."	Interfaces 3D - Creo	20.1.4.0
8003328	There is no STEP (*.stp; *.step; *.STP; *.STEP) under File type list when Load or Save file in Creo Elements/Direct Modeling 20.1 on Windows 7, but 18.0 works well.	Interfaces 3D - STEP	20.1.4.0
6383780	Japanese localization issue for "sd_cadcam.ms" file in Creo Elements/Direct Modeling	Machining Features	20.1.4.0
7237617	Performance issues in Windows 10 with CMT and context menu	Modeling	20.1.4.0
10041665	Part Library activation shows LISP error.	PartLibrary	20.1.4.0
7844079	Option setting of publishing rule "FitToPaper" does not work effectively	Plot / Print Modeling	20.1.4.0
9552763	Unfolding a certain model results in Creo Elements/Direct Modeling has stopped working	Sheet Metal - Fold/Unfold	20.1.4.0
9875411	When clicking the command buttons for dimensions, it takes 1-2 seconds to complete the display of the dialog in Annotation	User Interface - Modeling	20.1.4.0
10019171	To provide an API to WGM to detect if Modeling is idle state and no commands are in process	User Interface - Modeling	20.1.4.0
2815873	LISP error: Unexpected end of #<string-input stream from "(docu::docu-fnc ...">. is returned when editing a string attribute value where the value contains a single or double quotes (' or ")	WGM for Modeling	20.1.4.0
4663646	Drop Number File Extension does not work for	WGM for	20.1.4.0

	Windchill Workgroup Manager for Creo Elements Direct Modeling 10.2 M010	Modeling	
6792113	Sheet number and scale wrong for multi-sheet drawings	WGM for Modeling	20.1.4.0
7340620	Endless hang when Activating and deactivating the Windchill Workgroup manager in Creo Element/Direct Modeling 20.0M030	WGM for Modeling	20.1.4.0
7483282	Lisp error: NIL is not of type DSM::SIMPLE-ENTITY when displaying drawing components	WGM for Modeling	20.1.4.0
7561015	Assembly Instance data fails to open in CEDM from WGM when preference "Default load type=Partial"	WGM for Modeling	20.1.4.0
7708408	WGM JSCB Automation Specific: SysID Conflict Window does not list the CEDM Instance data when data is opened from ->Add CAD tool command -> Open	WGM for Modeling	20.1.4.0
8237628	Change Load type fails with error message : "Change Loadtype failed"	WGM for Modeling	20.1.4.0
8423448	sd-uwgm-element-load delivers wrong return-value	WGM for Modeling	20.1.4.0
9329694	Temporary deactivation of the autonumbering using SET-PREDICT-NAMES-ON-CREATE does not work anymore	WGM for Modeling	20.1.4.0
9514800	Drawing load in CEDM from WGM is degraded by ~ 3-4 times	WGM for Modeling	20.1.4.0
9523553	Save to WS fails after doing Undo & Redo on a Drawing loaded in Annotation session.	WGM for Modeling	20.1.4.0
9529434	Modified flag not seen for models modified in session after 'Compare model versions' workflow.	WGM for Modeling	20.1.4.0
9561942	Modified flag not set even after object is modified in session when opened specifically from 'Open from Windchill'.	WGM for Modeling	20.1.4.0
9648672	Unnecessary Drawing updates after loading in Windchill Workgroup Manager for Creo Elements/Direct Modeling	WGM for Modeling	20.1.4.0
9683581	Prevent user from creating Invalid Characters in File Name of CEDM Structure browser in connected mode	WGM for Modeling	20.1.4.0
9927127	Incorrect logging created due to 'set_model_property' may lead to a crash CEDM in certain cases.	WGM for Modeling	20.1.4.0

©2020 PTC Inc. The information contained herein is provided for informational use and is subject to change without notice. The only warranties for PTC products and services are set forth in the express

warranty statements accompanying such products and services and nothing herein should be construed as constituting an additional warranty. PTC shall not be liable for technical or editorial errors or omissions contained herein. Important Copyright, Trademark, Patent, and Licensing Information: See the About Box, or copyright notice, of your PTC software.