Fixes and Enhancements Creo Elements/Direct[®] Modeling 20.6.2.0

Please find below the list of fixes and enhancements - as of May 21st, 2024 - that have been implemented for Creo Elements/Direct Modeling and Creo Elements/Direct 3D Access 20.6.2.0.

NOTE:

The relations solver has been enhanced in Creo Elements/Direct Modeling 20.3 to provide improved solutions for assembly and parametric relations especially for cases involving tangential transitions within fully constraint model geometry. At the same time this might lead to differently calculated solutions for under-constrained relation sets.

This change might therefore affect existing animations created with previous versions of Creo Elements/Direct Modeling containing relations or involving positional movement of parts. Existing animations capturing positions of models moved by dragging using 3D Copilot could yield in slightly different final positions of the models.

ID	Module	Description	Release
14363245	3D Access	Annotation drawing does not Fit properly in	Modeling
		viewport. Zoom also does not work correctly.	20.6.0.0
		Dragging the window causes screen flickering.	
12038272	Advanced Design	Simplified geometry is converted to Face part after	Modeling
	Simplification	running Associate command in Simplification	20.6.0.0
		module.	
14203382	Analysis &	Error message appears and Aux VP closes if light	Modeling
	Checks	source properties are changed on Aux VP during	20.6.0.0
		the execution of Clash commands in Creo	
		Elements/Direct Modeling	
14217232	Analysis &	When using the function "get_vol_prop" on a part in	Modeling
	Checks	an assembly and then move the part out of the	20.6.0.0
		assembly and check the empty assembly with the	
		same function then the mass of the before selected	
		part is shown in Creo Elements/Direct Modeling	
10188304	Annotation	Commands of the Mini Toolbar must be selected	Modeling
		multiple times to invoke the command at large views	20.6.0.0
12730547	Annotation	Deactivated Sheet Metal leads to wrong "Flat View"	Modeling
			20.6.0.0

12769215	Annotation	Undo leads to an error	Modeling 20.6.0.0
13738052	Annotation	Apply of "Modify Text" or "Modify Ref Line" doesn't update the dimension completely	Modeling 20.6.0.0
13866948	Annotation	Edit Multi language settings action to be done on OK/Cancel button.	Modeling 20.6.0.0
13866976	Annotation	Table Info UI in ML table does not close on hitting Save button.	Modeling 20.6.0.0
13934226	Annotation	Multiline text for Dimension is displayed in a single line when the option 'Display in separate line = N0'.	Modeling 20.6.0.0
13934235	Annotation	The text size and colour for secondary language is not consistent across the multiline for GDT symbol when the option 'Display on separate lines = N0'.	Modeling 20.6.0.0
13981247	Annotation	Customized shortcut key to invoke ML table does not override the original shortcut key.	Modeling 20.6.0.0
14013702	Annotation	Split bolt circle causes problem when exporting drawing to DXF, DWG or Iges2D in	Modeling 20.6.0.0
14326345	Annotation	Japanese translation: "Attach drawing to Copy" command description is incorrect Creo Elements/Direct Modeling	Modeling 20.6.0.0
14381772	Annotation	Inspection label and inspection rate in the Global settings should be renamed to inspection prefix and inspection postfix.	Modeling 20.6.0.0
14381781	Annotation	Unable to change colour of Inspection label and inspection rate (prefix and postfix).	Modeling 20.6.0.0
14415153	Annotation	"Apply Multi-Language Settings" strings is truncated on Load dialog	Modeling 20.6.0.0
14419768	Annotation	Top right x button of Edit Multi Lang settings dialog closes all the dialog.	Modeling 20.6.0.0
14419784	Annotation	Multiple times launching Edit Multi Lang settings dialog opens multiple dialog one on top of other.	Modeling 20.6.0.0
14422528	Annotation	Higher resolution icons for Multi Lang.	Modeling 20.6.0.0
14469111	Annotation	No icon is shown for Unhighlight command in 'Recent commands' toolbar in Annotation for Multilanguage context.	Modeling 20.6.0.0
14502788	Annotation	Undo/Redo does not work for indicators in annotation.	Modeling 20.6.0.0
14029087	Annotation - Dimension	Dimension line is missing for linear and Radial/Diameter dimension created and dimension value is moved out of extension line.	Modeling 20.6.0.0
14127090	Annotation - Dimension	The dimension text's gap and space changes when changing the reference of a surface symbol while the surface symbol and the dimension is grouped	Modeling 20.6.0.0
14170917	Annotation - Dimension	Edit Language settings in ML does not work with Inspection dimension - Prefix/Postfix.	Modeling 20.6.0.0
14170921	Annotation - Dimension	No option of copy To / From for Inspection dimension in Dimension properties.	Modeling 20.6.0.0

14175054	Annotation - Dimension	Dropdown list of Prefix/Postfix of Inspection dimension does not store the previous values (list of	Modeling 20.6.0.0
		20).	
14515611	Annotation -	Dimensions are shown as dangled when bdl files	Modeling
	Dimension	with Inspection dimension created with ISO are	20.6.0.0
		reloaded in Annotation.	
14518996	Annotation -	Inspection element (dim) Box does not resize in	Modeling
	Dimension	Multi Lang support; at max font size of secondary	20.6.0.0
		language	
12752511	Annotation -	Chinese Simplified: Corrupted string in Exported	Modeling
	Drawing & Sheet	BOM Table in Drawing.	20.6.0.0
13900152	Annotation -	When using the "Multi Language" function in	Modeling
	Drawing & Sheet	Annotation the "Show Setting" "Act Owner" does not	20.6.0.0
		work for the translated text	
13900220	Annotation -	When using "Multi-Language" Texts and switching	Modeling
	Drawing & Sheet	on "Highlight Multi-Language Elements" the "Show	20.6.0.0
		Option" for "Act Owner" does not work anymore	
14038862	Annotation -	LISP error is displayed while copying sheet with	Modeling
	Drawing & Sheet	Dimensions having ML and Inspection rate.	20.6.0.0
14043930	Annotation -	Copy sheet command does not copy Surface finish	Modeling
	Drawing & Sheet	and Welding symbols.	20.6.0.0
14061868	Annotation -	GDT, Surface and Welding symbols created with	Modeling
	Drawing & Sheet	Sheet as owner cannot be copied to new sheet	20.6.0.0
	J J	using Copy Sheet command.	
12440386	Annotation - Filing	Creo Elements/Direct Modeling Annotation and	Modeling
	0	Creo Elements/Direct Drafting cannot load the	20.6.0.0
		attached dxf file and when loading it, Annotation	
		and Drafting become unresponsive.	
14072730	Annotation -	It is not possible in "Annotation" to change the	Modeling
	Settings	default colour setting of "Bolt Circles"	20.6.0.0
14188666	Annotation -	Strings in Molding symbol UI disappears after	Modeling
	Symbol	shuffling the fields in 'Form'.	20.6.0.0
14188678	Annotation -	Flipping the symbols in Moulding symbol UI mirrors	Modeling
	Symbol	the letters on the symbol n drawing.	20.6.0.0
14318615	Annotation -	Edge Indication Dialog TITLE shows wrong	Modeling
	Symbol	Standard (shows moulding standard).	20.6.0.0
14321505	Annotation -	Scroll arrow at top/bottom of symbols UI is missing	Modeling
	Symbol	in Annotation.	20.6.0.0
14331398	Annotation -	The colour fields does not disappear while	Modeling
	Symbol	collapsing Appearance in Edge symbol UI in	20.6.0.0
		Template browser.	
14410729	Annotation -	When in "Annotation" the "Owner" of a "Symbol" is	Modeling
	Symbol	changed then the "Symbol" is exploded into its	20.6.0.0
		component elements	
14419791	Annotation -	Moulding REF line value of symbol d and b remains	Modeling
	Symbol	there for other forms where symbol d is not even	20.6.0.0
	,	valid like form (5th from the dropdown)	
14465699	Annotation -	LISP error is displayed in Annotation after doubling	Modeling
	Symbol	clicking the Surface symbols from Examples group	20.6.0.0
		i che canace cynisole noni Examplee gloup	

14522343	Annotation -	Option missing to mention '5x' in Moulding refline	Modeling
	Symbol	symbol in Template browser of Annotation module.	20.6.0.0
13493886	Annotation - Text	When creating a text reference line in Annotation	Modeling
		deleting it and executing undo command a circle is	20.6.0.0
		created on the reference line	
14332502	Annotation - Text	When using the command Copy Text and copy a	Modeling
		text with two lines, the copied text is changed to a	20.6.0.0
		multi language text	
14416153	Annotation - Text	When a Text with two lines is copied in	Modeling
		Annotation the font size and colour of the second	20.6.0.0
		line will change	
14521173	Annotation - Text	Option to insert multiline language text is not	Modeling
		available while modifying a text symbol	20.6.0.0
14521207	Annotation - Text	Error displayed while inserting multilanguage text in	Modeling
		text editor	20.6.0.0
7988073	Annotation - View	Annotation View Copy: Detail view text is not	Modeling
		updated while copying view from one sheet to	20.6.0.0
		another.	
12646935	Annotation - View	Section view arrows are displayed in wrong	Modeling
		orientation	20.6.0.0
14243567	Annotation - View	When using the function "Section Line Modify" in	Modeling
		Annotation "Move" and "Horizontal" the direction of	20.6.0.0
		the arrows flips into the other direction in Creo	
		Elements/Direct Modeling	
14305958	Annotation - View	Performance, important suggestions for	Modeling
		improvement in Annotation	20.6.0.0
13012302	Annotation - View	Signal during view update of a specific drawing	Modeling
	Update		20.6.0.0
6475869	Base	The drawing disappears when switching to	Modeling
	Functionality -	Annotation after saving to STEP	20.6.0.0
	Modeling		
8049126	Base	Some parts from the assembly created in Creo	Modeling
	Functionality -	Elements/Direct with the help of Rigid Cable Advisor	20.6.0.0
0.4000.40	Modeling	are missing when opened in Creo Parametric	
8420310	Base	In non-English help centre, Quick Start Project	Modeling
	Functionality -	video links to English version	20.6.0.0
40707047	Modeling		
12707017	Base	Create Analysis leads to LISP Error	Modeling
	Functionality -		20.6.0.0
40740000	Modeling	No success of the local offer locality of OD	
12718968	Base	No error message is displayed after loading of 3D	Modeling
	Functionality -	instance data assembly with parts missing.	20.6.0.0
12740655	Modeling Base	Mass calculation leads to a crash	Modeling
12140000			Modeling
	Functionality -		20.6.0.0
10001050	Modeling	Cree Flemente/Direct Medeling and Droffing 00.4	Madalia
12881850	Base	Creo Elements/Direct Modeling and Drafting 20.4	Modeling
	Functionality -	can be launched with Creo Elements/Direct License	20.6.0.0
	Modeling	Server 20.3 if there is the license of Creo	
		Elements/Direct 20.4 in "License.conf"	

13364344	Base	When switching between Modeling and Annotation	Modeling
	Functionality - Modeling	the width of Structure Browser is changing randomly	20.6.0.0
14042075	Base	For CEDM "Workplane" data during worker	Modeling
	Functionality - Modeling	publishing causes worker error and job fails.	20.6.0.0
14101421	Base	Missing conversion related logging information for	Modeling
	Functionality - Modeling	CEDM Container parts.	20.6.0.0
14163865	Base	Publishing when license is not available for different	Modeling
	Functionality - Modeling	file types during additional file conversion is handled.	20.6.0.0
14408289	Base	The "Structure Browser" disappears when executing	Modeling
	Functionality - Modeling	"Save" or "Open" command	20.6.0.0
14520973	FEA	In Finite Element Analysis the symbol size of Mating	Modeling
		Relation cannot be changed by Settings > Symbol	20.6.0.0
		Size > Global Sym Size in Creo Elements/Direct Modeling	
13857486	Filing - Modeling	Visually similar 3D Models have big differences in file size	Modeling 20.6.0.0
9911646	Graphics -	Econo-Crash' test of Creo Elements/Direct Modeling	Modeling
	Modeling	causing app-hang/crash On HG laptops. [Customer SPR]	20.6.0.0
14049349	Installation -	Legacy name change for Unigraphics Install	Modeling
	Modeling	wizard of CAD adapters - NX	20.6.0.0
14061511	Installation - Modeling	While installing the Modeling, error is thrown for Creo 9 platform install.	Modeling 20.6.0.0
14135881	Installation -	Installation of Version 20.4 and 20.5 requires non-	Modeling
	Modeling	supported Microsoft redistributable of Visual Studio 2008	20.6.0.0
12730654	Integration Kit	SD-XML-TRANSFORM-FILE throws a Lisp error	Modeling
		when called as documented	20.6.0.0
9341721	Interfaces - DWG/DXF	dxfdwg readme version 20.2 is missing in Modeling 20.2.0.0	Modeling 20.6.0.0
13617049	Interfaces -	The log file output after dxfdwg file conversion	Modeling
	DWG/DXF	differs from the dxfdwg.con file settings	20.6.0.0
13365672	Interfaces 2D	When loading a Drafting MI drawing into Annotation	Modeling
		staggered dimensions are displayed wrong	20.6.0.0
13719441	Interfaces 2D	Modeling fails to generate Multi-fidelity OL files.	Modeling 20.6.0.0
13744900	Interfaces 2D	Publishing a .mi file using a publish rule results in	Modeling
107		incorrect PDF and DXF	20.6.0.0
13792503	Interfaces 3D	XVL Converter Ver.18.1 OEM module is supported	Modeling
		for CEDM 20.4.2.0 onwards.	20.6.0.0
14095728	Interfaces 3D	Additional output file format creation fails if invalid	Modeling
-	_	value is passed as file version.	20.6.0.0
14383548	Interfaces 3D	2D geometry is not shown in eDrawings 2023 when	Modeling
		importing the edrw file saved from Annotation with	20.6.0.0
		option 'Export shaded data' unchecked.	

13451193	Interfaces 3D - Creo	New parameters: CED_Stock_Container True (for stock/finish container) and CED_Simplification_Container True (for	Modeling 20.6.0.0
		simplification container)	
13575005	Interfaces 3D -	Selective instance is not considered during open of	Modeling
	Creo	CED data with config.pro option	20.6.0.0
	0.00	"sync data import profile update"	20101010
13757376	Interfaces 3D -	Native Granite import of *.asm/*.prt files successful	Modeling
	Creo	but delivers damaged models in Creo	20.6.0.0
		Elements/Direct Modeling	
13816667	Interfaces 3D -	PVZ export fails for Empty part with option 'Export	Modeling
	Creo	empty part' checked and option 'adapter/output	20.6.0.0
		AnnotPlanar = 0' in recipe fie.	
13966492	Interfaces 3D -	Import of .pkg file coming from Creo	Modeling
	Creo	Elements/Direct Modeling results in empty geometry	20.6.0.0
		in Creo Parametric 8.0	
14163428	Interfaces 3D -	Creo Elements/Direct Modeling assembly opened	Modeling
	Creo	from Workspace in Creo Parametric does not show	20.6.0.0
		the correct transparency applied, rather shows	
		default transparency	
14263732	Interfaces 3D -	Creo Simulate interface to be renamed as 'Creo	Modeling
	Creo	Parametric Simulation Extension'.	20.6.0.0
14323819	Interfaces 3D -	Creo Path population based on the registry entry of	Modeling
	Creo	installed Creo in Creo Simulate module.	20.6.0.0
14110859	Licensing -	Message "Upgrade of 20.5.0.0" is shown when	Modeling
	Modeling	MEIs 20.6.0.0 is installed.	20.6.0.0
14185125	Licensing -	Backup tab is not visible in Primary server status	Modeling
	Modeling	page with https config.	20.6.0.0
14185258	Licensing -	Backup server should be listed as hostname instead	Modeling
	Modeling	of IP address in status page.	20.6.0.0
14317012	Model Manager	Saving ".mi" drawing into "Model Manager" from	Modeling
	Integration	"Annotation" in an older version than 20.5 (i.e. 20.4)	20.6.0.0
		results in "Nullpointer Exception" message in Creo	
		Elements/Direct Model Manager	
6378655	Modeling	New function's video for Creo Elements/Direct	Modeling
		Modeling 20 is not uploaded to "PTC University	20.6.0.0
		Learning Exchange", but HELP Centre says "Watch	
		a video on PTC University Learning Exchange"	
13599797	Modeling	CEDM "Workplan" data to generate 3d additional	Modeling
		files i.e. IGES, Inventor, STEP etc., causes worker	20.6.0.0
40050400		timeout and publishing job fails	
13856186	Modeling	OL file generation of a 3D File runs in an endless	Modeling
40007447			20.6.0.0
13867117	Modeling	Few pkg files are failed to publish using Creo View	Modeling
4000000		Adapter X-90 & X-91.	20.6.0.0
13983987	Modeling	CEDM worker hang issue is observed when license	Modeling
		is not available, for INVENTOR option from	20.6.0.0
		additional file conversion	

14038441	Modeling	After modifying Simplification container to Regular	Modeling
		container, icon should be changed to regular container icon in MM.	20.6.0.0
14086646	Modeling	Updated MM status in Modeling Structure browser is not seen.	Modeling 20.6.0.0
14247614	Modeling	This issue only occurs in Creo Elements/Direct Modeling 20.5.1.0.	Modeling 20.6.0.0
14509916	Modeling	For a selective instance data inside an assembly, unique comp ID is not seen same as Windchill ID	Modeling 20.6.0.0
14514181	Modeling	For attached dataset, configuration defined does not show up correctly with component ID enabled.	Modeling 20.6.0.0
14519267	Modeling	Simplification container showing wrong icon when user disable "Load Simplification Container" in User Preferences and save the model.	Modeling 20.6.0.0
13167867	Modeling Integration	[Creo Unite] Opening a modified/updated CEDM assembly in Creo Parametric fails or is loaded with errors in Creo session, the updates from CEDM session are not reflected	Modeling 20.6.0.0
13860516	Modeling Integration	When importing specific migrated Creo Elements/Direct Modeling assemblies in Creo Parametric, the parameter CED_CONTAINER is not created for containers	Modeling 20.6.0.0
12037847	PartLibrary	Part Library: Observed unexpected error message while using "Create Pipes" command in Part Library.	Modeling 20.6.0.0
12779100	PartLibrary	Help from the menu of some SolidPower commands does not work	Modeling 20.6.0.0
13249038	PartLibrary	Segmentation violation occur after PartLibrary feature rotation	Modeling 20.6.0.0
12744338	Pattern	Pattern creation of a hole with tolerance applied, returns a LISP Error	Modeling 20.6.0.0
5223679	Plot / Print Modeling	The generated PDF viewable is not scaled to FIT when publishing a Creo/Elements Direct Drafting drawing	Modeling 20.6.0.0
12702174	Sheet Metal	It is not possible to open the Help Centre for several commands	Modeling 20.6.0.0
13048635	Sheet Metal	Unfold 2D leads to incorrect result for a part with chamfers	Modeling 20.6.0.0
14468330	Sheet Metal	Sheet Metal: Modify Material fails when working with old Sheet Metal part	Modeling 20.6.0.0
11356412	WGM for Modeling	After selecting option 'Reload' for SYSID conflict, show irrelevant WGM message "Models are not checked out"	Modeling 20.6.0.0
12740887	WGM for Modeling	Stock Finish Relation file gets loaded as Multi version data after applying Assign New SysID	Modeling 20.6.0.0
12744578	WGM for Modeling	New ID/Old ID are not externalized on assign SysID dialog	Modeling 20.6.0.0
12760061	WGM for Modeling	CEDM Annotation Bom Table: special characters are displayed as squares in the BOM Table	Modeling 20.6.0.0

12770585	WGM for Modeling	In Session Data Corruption: The component which was integrated in an Inseparable Assembly when	Modeling 20.6.0.0
13171796	WGM for Modeling	 separated out is not treated as new in session. "Assign New SysID" & commands mentioned in the Description should be either not available / should not work in Annotation Module. 	Modeling 20.6.0.0
13247857	WGM for Modeling	Data gets modified in session even when it is Locked in CEDM session when IBA value is assigned in structure browser.	Modeling 20.6.0.0
13386471	WGM for Modeling	Preselect corrupts Creo Elements Direct Modeling objects in a linked session to Windchill	Modeling 20.6.0.0
13519451	WGM for Modeling	Assign New SysID does not work on Surface Parts	Modeling 20.6.0.0
13519913	WGM for Modeling	When the Workgroup Manager is activated, the structure browser flickers when models are positioned	Modeling 20.6.0.0
13539649	WGM for Modeling	Modeling Crash seen after Assign New SysID is done on Partially loaded recursive data followed by Revert action	Modeling 20.6.0.0
13739839	WGM for Modeling	ND information is not applied to CEDM session after SYSID conflict resolution	Modeling 20.6.0.0
13744965	WGM for Modeling	Assign New SysID Info Message strings are not on separate line. They are separated by ~%	Modeling 20.6.0.0
13757833	WGM for Modeling	Table option: Error thrown while assigning PosFlags for WTPartless Sub Assembly whose mainAssembly is under another "Top Level" Assembly	Modeling 20.6.0.0
13796240	WGM for Modeling	Data does not get modified flag, even if actual geometrical modifications are done in session, when data is opened specifically from Annotation module.	Modeling 20.6.0.0
13798217	WGM for Modeling	Highlighting does not work as expected when a single level BOM is exported to session having Sub- Assembly, Top Level Assembly & Individual components views	Modeling 20.6.0.0
13800846	WGM for Modeling	After loading the second drawing into Creo Elements / Direct Modeling Annotation, a warning message occurs even if the first drawing hasn't been edited	Modeling 20.6.0.0
13806554	WGM for Modeling	Activating a Workspace takes much longer when Creo Elements/Direct Modeling is running connected to Windchill Workgroup Manager as compared to when only the Workgroup Manager is running	Modeling 20.6.0.0
13812454	WGM for Modeling	Pos Flags does not get generated with the new dataset provided by OPTIMA	Modeling 20.6.0.0
13821697	WGM for Modeling	When New View is created, Pos Flags cannot be determined for New or Old Views.	Modeling 20.6.0.0
13821828	WGM for Modeling	Shared Instances do not highlight correctly, when a Sub-assembly BOM Report having shared	Modeling 20.6.0.0

		Instances is exported to a Drawing having Top Assembly Parent View.	
13853763	WGM for Modeling	Modeling goes in endless error loop, when a BOM report is exported to session having corresponding Top Level Assembly with No Extension in Name field. Creating a new CEDM session does not reproduce issue.	Modeling 20.6.0.0
13858114	WGM for Modeling	Modified Flag is not set on the Drawing, even if it's modified when Annotation drawing is created in a specific workflow	Modeling 20.6.0.0
13858195	WGM for Modeling	If Sub-Assembly is loaded in Lightweight mode, BOM Export throws an Error in endless loop which would require CEDM to be closed losing all unsaved work.	Modeling 20.6.0.0
13935803	WGM for Modeling	Resolving Partially loaded Recursive ref. Container which gets moved using MODIFY OWNER after doing Assignee New SYSD crashes CEDM	Modeling 20.6.0.0
13974379	WGM for Modeling	Change Load Type fails for any Load Type when done for any data other than Top Level data, after Compare Model Version is done.	Modeling 20.6.0.0
13979970	WGM for Modeling	When Default Load type is set to Lightweight, placing a Library Part in CEDM session thrown an error.	Modeling 20.6.0.0
13980626	WGM for Modeling	Data does not get loaded in Partial mode when opened using the HTML Open in CAD tool action.	Modeling 20.6.0.0
13994395	WGM for Modeling	Data does not get loaded in Partial mode when opened using the LISP Command Interface.	Modeling 20.6.0.0
14030722	WGM for Modeling	Opening Creo Authored CEDM data from WGM to CEDM when CEDM is not running, opens the data but HANGS CEDM.	Modeling 20.6.0.0
14051193	WGM for Modeling	Irrelevant NPD Error is thrown, when a Library Part is placed in session & Load Type is set to Partial mode.	Modeling 20.6.0.0
14144116	WGM for Modeling	Load type of just created and checked in part in Creo Elements Direct Modeling cannot be changed	Modeling 20.6.0.0
14166728	WGM for Modeling	WGM lisp function returns incorrect component id for CEDM shared parts and assemblies	Modeling 20.6.0.0
14224536	WGM for Modeling	PDM actions are possible on data which is having Recursive References. Doing this results in CEDM becoming unstable and crashes with FATAL exception.	Modeling 20.6.0.0
14313040	WGM for Modeling	The creation of a Stock-Finish-Part-Relation in a defined Design-Process not possible	Modeling 20.6.0.0
14408446	WGM for Modeling	Container under part gets loaded incorrectly, even when container loading is set to Full mode.	Modeling 20.6.0.0
14409149	WGM for Modeling	Shared data under Assembly gets loaded in Partial mode, even when loading is set to Full mode.	Modeling 20.6.0.0
14500749	WGM for Modeling	Drawing-Frame offset not maintained when data is opened after Reuse of Frames using Import to Workspace.	Modeling 20.6.0.0

14513923	WGM for Modeling	Doing Change Load Type on data in session does not work for dependent nodes when revert is done	Modeling 20.6.0.0
5937324	Workplanes/Work planeSets	on its parent node. Cannot select many 2D edges to be projected onto another workplane in Creo Elements/Direct Modeling	Modeling 20.6.0.0
13306463	Interfaces 3D	After store a file in eDrawings professional format the software raises the message Error LISP: Improper number vector syntax at every graphical pick or graphical selection	Modeling 20.6.1.0
13520019	Annotation - Dimension	Dimension fix texts are taken over to next dimension where it shouldn't	Modeling 20.6.1.0
13652721	Annotation - View Update	When adding a view to a drawing where the owner is an inseparable object the existing views need to be updated	Modeling 20.6.1.0
13805113	Interfaces 3D	Double clicking the viewables repositions the content outside the viewable area in Creo View	Modeling 20.6.1.0
14062003	WGM for Modeling	When a Drawing is opened from WGM & when CEDM is not running, Drawing gets opened in session with modified flag.	Modeling 20.6.1.0
14164789	Base Functionality - Modeling	Wvs Job logs For Additional file format conversion for drawings in case of error reporting Shows as "Converting Model to Format INVENTOR"	Modeling 20.6.1.0
14470453	WGM for Modeling	Table range/subrange selection does not work asexpected in Creo Elements Direct Modeling	Modeling 20.6.1.0
14509916	Modeling	[NF] For a selective instance data inside an assembly, unique comp ID is not seen same as Windchill ID	Modeling 20.6.1.0
14519062	WGM for Modeling	Inseparable icon of the parent node is not seen in CEDM session, when data is saved to workspace	Modeling 20.6.1.0
14331394	WGM for Modeling	When configuration is made active and Change load type is done, the top level Instance gets modified in session.	Modeling 20.6.1.0
14445772	WGM for Modeling	Custom Part/Assembly Library always creates Top Level Instance with same File Name "New.sda"	Modeling 20.6.1.0
14443978	WGM for Modeling	Library data with same SysID is unnecessarily asked for Check Out when Save to WS is done from Annotation	Modeling 20.6.1.0
14604634	WGM for Modeling	REGRR [from CEDM 20.5.1.0] : Even when Assembly is loaded in Full mode, modifications are not allowed and an error is thrown.	Modeling 20.6.1.0
14606771	WGM for Modeling	Update of top Assembly in Modeling session with Windchill Workgroup Manager is failing	Modeling 20.6.1.0
14608953	Annotation - Symbol	[REGRESSION] In "Annotation" the width of dialog boxes for "Symbols" cannot be changed anymore in Creo Elements/Direct Modeling	Modeling 20.6.1.0

14610344	WGM for Modeling	When trying to copy an element that has a partially loaded subassembly which was loaded with Workgroup Manager root cannot be selected as owner in Creo Elements/Direct Modeling	Modeling 20.6.1.0
14617508	Interfaces 3D - Creo	When exporting 3D data as PVZ the error save_pv/signal/sigsegv occurs	Modeling 20.6.1.0
14619335	WGM for Modeling	[REGRESSION] Reload of lightweight model does not work correctly since version 20.5.1.0	Modeling 20.6.1.0
14673727	Annotation - Text	[REGRESSION] When trying to edit a text in "Annotation" the error message "LISP error: The function DOCU::SET-MULTI-LANG-RIGHT-CLICK- INSERT-ALLOWED is undefined" appears in Creo Elements/Direct Modeling	Modeling 20.6.1.0
14674003	Annotation - Text	In "Edit Text" commnad, LISP error "The function DOCU::SET-MULTI-LANG-RIGHT-CLICK-INSERT- ALLOWED is undefined"	Modeling 20.6.1.0
14697934	Annotation - Drawing & Sheet	When loading a drawing with multiple sheets (it occurs with all multi-sheet-drawings), additional frames are added, and these are then empty (it doesn't' occur with single sheets)	Modeling 20.6.1.0
14716639	Annotation	Annotation becomes unresponsive when attempt to place user defined symbol without an Annotation drawings	Modeling 20.6.1.0
14468626	WGM for Modeling	Saving a drawing with same File Name with options "Continue" or "Reload" does not work	Modeling 20.6.1.0
14789624	PartLibrary	Critical vulnerability in Ghostscript gswin32c.exe and gsdll32.dll	Modeling 20.6.1.0
14812226	WGM for Modeling	Selective Instance modifications are stored in the Top Level Assembly Content instead of Top Level Instance	Modeling 20.6.1.0
14822960	Annotation - Text	When a "Text" with two lines is saved as a template with command "Define Text as Template" in "Annotation" the font size and color of the second line will change in Creo Elements/Direct Modeling	Modeling 20.6.1.0
14829379	Base Functionality - Modeling	AR "Publish Model" and "Manage Model" are not available in Creo Elements/Direct Modeling.	Modeling 20.6.1.0
14842200	Installation - Modeling	Security vulnerability for 7za.exe	Modeling 20.6.1.0
14845467	Licensing - Modeling	Support MEIs with latest NGINX version.	Modeling 20.6.1.0
14869288	Annotation - Dimension	In Annotation, when a dimension is placed when creating a dimension, it is highlighted in Creo Elements/Direct Modeling	Modeling 20.6.1.0

7938853	PCB/IF	Information about " Clean Geo" option under Creo Elements/Direct PCB module not documented in PTC Help Center	Modeling 20.6.1.0
9107113	Annotation - Filing	Some variables from DXFDWG Configurator UI are not captured in *.con file.	Modeling 20.6.1.0
9873767	Annotation - View	Unable to create a new Annotation 2D View if temp disk space is larger than 2TB	Modeling 20.6.1.0
13755503	Base Functionality - Modeling	CEDM occurrence values are propagating to different component ID after publishing, this also causes issue in cad-wt part compare	Modeling 20.6.1.0
14406923	Modeling	CEDD: Publish multi sheet mi file as DXF output, then all sheets are publishing in sheet1.	Modeling 20.6.1.0
14520232	Modeling	CEDM DAPI toolkit update to CV 10.0	Modeling 20.6.1.0
14585920	Interfaces 3D	COCRMOD worker configured with CEDM 20.5.1 is unable to process larger assemblies	Modeling 20.6.1.0
14603489	Modeling	For wvs publishing, created paj file does not masked Password immediately and file with failed job.	Modeling 20.6.1.0
14665737	Modeling	Unable to save newly selected Master 2D to Model Manager	Modeling 20.6.1.0
14816690	Interfaces 3D	When trying to export 3D data as PVZ the error message "Action failed save_pv/signal/sigsegv" occurs in Creo Elements/Direct Modeling	Modeling 20.6.1.0
14830274	WGM for Modeling	Changing Load Type throws error for any Load Type specifically when WGM module is activated later for any Assembly having subassembly and children under it.	Modeling 20.6.1.0
14849823	Installation - Modeling	CEDM 20.4.4.16: Update File version/Product version for these two binaries SD.exe and SDkill.exe.	Modeling 20.6.1.0
15041219	Annotation	Issue observed in absolute size in Edge and Moulding Symbol	Modeling 20.6.2.0
15043821	Annotation - Symbol	Absolute size of symbol text of Moulding and Edge symbols does not reflect the changes made, while relative size does.	Modeling 20.6.2.0
15060181	Annotation - Symbol	Relative size of symbol is not working correct. The symbols get doubled on clicking Apply and then OK tick mark.	Modeling 20.6.2.0
9873767	Annotation - View	Unable to create a new Annotation 2D View if temp disk space is larger than 2TB	Modeling 20.6.2.0
14321963	Base Functionality - Modeling	Support multi-byte characters for CEDM CVA support	Modeling 20.6.2.0

14881007	Base Functionality - Modeling	When importing a 2D file from Japanese name's folder or a 2D file whose file name includes Japanese with Import 2D to workplane (*mi; *lyt; *dwg; *dxf), the following error will be generated	Modeling 20.6.2.0
14904594	Base Functionality - Modeling	Importing '0.pkg' file and '1.pkg' file in Modeling shows error.	Modeling 20.6.2.0
15061986	Base Functionality - Modeling	AR published models does differ on the basis of Viewable quality - low, medium, high. The recipe files from "prodview" folder are not picked programmatically for creating pvz files.	Modeling 20.6.2.0
15385811	Filing - Modeling	LISP error is shown on hitting 'All Objects' option on Save dialog while exporting files with extension *.sd*, *.stp, *.pvz, etc	Modeling 20.6.2.0
14849823	Installation - Modeling	Update File version/Product version for these two binaries SD.exe and SDkill.exe.	Modeling 20.6.2.0
14901729	Installation - Modeling	Modeling critical vulnerability - affects DoD	Modeling 20.6.2.0
14954662	Installation - Modeling	CED 20.4: To package recipe editor with CED installation	Modeling 20.6.2.0
14202299	Integration Kit	"sd-return-to-model-checkpoint" function not working in Creo Elements/Direct Modeling	Modeling 20.6.2.0
9728552	Interfaces - DWG/DXF	DXFDIR path won't be recognized in Creo Elements/Direct Modeling	Modeling 20.6.2.0
15190373	Interfaces 2D	Import 2D to Workplane failing for files containing Japanese characters.	Modeling 20.6.2.0
14816908	Interfaces 3D	When loading "PVZ" models which were created in "Creo Elements/Direct Modeling" holes and blends are shown as squares in Creo View	Modeling 20.6.2.0
14827199	Interfaces 3D	AR publishing fails when Creo View MCAD module is removed from Startup list in Modules.	Modeling 20.6.2.0
14945027	Interfaces 3D	XVL Converter Ver.21.0 OEM module support for 20.5 and 20.6.	Modeling 20.6.2.0
11183449	Interfaces 3D - Creo	Empty part node is created in structure browser when Quilt option is unchecked during loading of Creo files.	Modeling 20.6.2.0
11183453	Interfaces 3D - Creo	Additional container node is created in structure browser when loading Creo file with Quilt option checked ON.	Modeling 20.6.2.0
12717279	Interfaces 3D - STEP	LISP Error occurs if the Option Direct is selected	Modeling 20.6.2.0
15204687	Interfaces 3D - STEP	Edge color is not retained when exporting and importing to a step file Creo Elements/Direct Modeling	Modeling 20.6.2.0

14603489	Modeling	For WVS publishing, created paj file does not masked password immediately with failed job.	Modeling 20.6.2.0
14897748	Modeling	CEDM Worker hang and fails with timeout if publishing user does not have valid windchill license.	Modeling 20.6.2.0
14915866	Modeling	Remove binaries irrelevant from CEDIRECT.	Modeling 20.6.2.0
15070985	Modeling	Positioning assembly representation with multi-byte file name for parts/sub-asm for a CEDM assembly does not load them in Creo View Client.	Modeling 20.6.2.0
15132157	Modeling	Windchill auth admin password is not masked for CEDM failed job scenario.	Modeling 20.6.2.0
15202332	Modeling	Creo View Adapter 11.0 configured in multibyte folder using CEDM 20.7.0.146 cannot publish mi drawing files. It is throwing "No write access for file".	Modeling 20.6.2.0
15121828	PartLibrary	Part Library showing incorrect version no.	Modeling 20.6.2.0
15072839	User Interface - Modeling	Viewport background image disappear after using a configuration or loading mode	Modeling 20.6.2.0
7524023	WGM for Modeling	Getting error "An orphaned inseparable object is found which cannot uniquely related to its inseparable master" while loading an inseparable assembly in Creo Elements/Direct Modeling	Modeling 20.6.2.0
13609695	WGM for Modeling	Views in Creo Elements/Direct Modeling Annotation drawings can be deleted while the owning 3D object is locked (in Workspace and session) - this should not be allowed	Modeling 20.6.2.0
14841361	WGM for Modeling	Unable to copy or move a model inside the structure	Modeling 20.6.2.0
14871550	WGM for Modeling	When WGM is active, an inseparable element (e.g. an assembly or container) is loaded, and a part inside the assembly is changed, this part is not marked with the modified flag/symbol	Modeling 20.6.2.0
14904429	WGM for Modeling	No Read Access Scenario: For pseudo partial (For part not available in Workspace)	Modeling 20.6.2.0
14954625	WGM for Modeling	Even when Container is loaded in Partial mode, data can creep in the structure and no designed error is thrown.	Modeling 20.6.2.0
14960640	WGM for Modeling	Container when loaded at root level with Load Type as Lightweight/Structure/Partial loads the Container in FULL mode & for Partial load also loads the structure below it in structure mode	Modeling 20.6.2.0
14963343	WGM for Modeling	Change Load Type & Icon Related Issue for Container in CEDM	Modeling 20.6.2.0

15025633	WGM for	Export List to CEDM in WGM fails with ERROR	Modeling
	Modeling	Message in CEDM:	20.6.2.0
		am_bom_scan3d_wgm/signal/sigsegv	
15062705	WGM for	Export List To CEDM in WGM fails with ERROR	Modeling
	Modeling	Message in CEDM:	20.6.2.0
		am_bom_scan3d_wgm/signal/sigsegv	
15109986	WGM for	Even after setting LISP function "(sd-uwgm-set-	Modeling
	Modeling	drawing-viewable-format :dwg :dxf)" Drawing is getting published always in pdf format.	20.6.2.0
15190240	WGM for	Container is loaded in Full load for recursive	Modeling
	Modeling	reference data with "File>Open from WC" action from CEDM.	20.6.2.0
15215665	WGM for	Subassembly parts data is loaded incorrectly when	Modeling
	Modeling	Assembly loading is changes from Full to Partial	20.6.2.0
	0	load type in CEDM session.	
15290950	WGM for	Inseparable icon of the parent node is not seen in	Modeling
	Modeling	CEDM session, when data is saved to workspace	20.6.2.0
15297063	WGM for	Reloading of a second A.1 asm results in model	Modeling
	Modeling	being displayed as new	20.6.2.0
15297129	WGM for	Structure Browser not getting updated after calling	Modeling
	Modeling	UNDO recorder through executeMacroCommand.	20.6.2.0
15375787	WGM for	When Containers gets loaded in Lightwegith/	Modeling
	Modeling	Structure mode, BOM export is not possible due to	20.6.2.0
	-	error message.	
8755370	Workplanes/Work	2D-Copilot will disappear when editing the second	Modeling
	planeSets	coordinate value on the workplane in Creo	20.6.2.0
		Elements/Direct Modeling	

©2024 PTC Inc. The information contained herein is provided for informational use and is subject to change without notice. The only warranties for PTC products and services are set forth in the express warranty statements accompanying such products and services and nothing herein should be construed as constituting an additional warranty. PTC shall not be liable for technical or editorial errors or omissions contained herein. Important Copyright, Trademark, Patent, and Licensing Information: See the About Box, or copyright notice, of your PTC software.